



CAUTION:
DO NOT DRILL THROUGH OR REMOVE CENTER GUIDE TRACK. IT MUST REMAIN INTACT FOR PROPER ROLLER PERFORMANCE.